

Lift Equipment Failure Incident reported to EMSD (Jan 2024 to Dec 2024)

Contractor No.	Name of Contractor	Incident Date	Location	Incident Nature
RLC74002	Schindler Lifts (Hong Kong) Ltd.	11/02/2024	Discovery Park, 398 Castle Peak Road, Tsuen Wan, N.T.	Passenger tripping due to levelling difference of lift car at landing arisen from malfunction of electrical component
RLC74002	Schindler Lifts (Hong Kong) Ltd.	08/04/2024	Seaview Mansion, 34 Kennedy Road, Mid-Levels, Hong Kong	Breakage of suspension belts due to lift car stuck in the liftway while the drive sheave was still revolving.
RLC75004	Otis Elevator Company (H.K.) Ltd.	06/05/2024	Hong Kong Adventist Hospital La Rue Building, 40 Stubbs Road, Happy Valley, Hong Kong	Occurrence of unintended car movement due to failure of brake system.
RLC75004	Otis Elevator Company (H.K.) Ltd.	30/05/2024	Tse On House, Yue On Court, 3 Yue On Court Road, Aberdeen	Passenger tripping due to levelling difference of lift car at landing arisen from malfunction of electrical component
RLC75004	Otis Elevator Company (H.K.) Ltd.	26/07/2024	1 Duddell Street, Central, Hong Kong	Passenger tripping due to levelling difference of lift car at landing arisen from malfunction of electrical component
RLC74002	Schindler Lifts (Hong Kong) Ltd.	07/08/2024	Wah Kwai Estate, Aberdeen, Hong Kong	Passenger tripping due to levelling difference of lift car at landing arisen from malfunction of electrical component
RLC74002	Schindler Lifts (Hong Kong) Ltd.	22/08/2024	Grand Millennium Plaza, Cosco Tower, Victoria Telephone Exchange, 183 Queen's Road Central, Central	Passenger tripping due to levelling difference of lift car at landing arisen from malfunction of electrical component
RLC74002	Schindler Lifts (Hong Kong) Ltd.	26/09/2024	Standard Chartered Bank Building, 4-4a Des Voeux Road Central, Central, Hong Kong	Occurrence of unintended car movement due to failure of drive control system.
RLC74002	Schindler Lifts (Hong Kong) Ltd.	09/10/2024	Kar Yam House, On Yam Estate, Kwai Chung	Passenger tripping due to levelling difference of lift car at landing arisen from malfunction of electrical component
RLC74002	Schindler Lifts (Hong Kong) Ltd.	15/11/2024	Discovery Park, 398 Castle Peak Road, Tsuen Wan, N.T.	Passenger tripping due to levelling difference of lift car at landing arisen from malfunction of electrical component
RLC74002	Schindler Lifts (Hong Kong) Ltd.	21/12/2024	Times Square, 1 Russell Street, Causeway Bay, Hong Kong	Passenger tripping due to levelling difference of lift car at landing arisen from malfunction of electrical component

No. of Equipment Failure Records = 11